



# Post-Construction Stormwater Management Inspection & Maintenance Manual

Central Virginia  
Community College



**June 2019**

3506 Wards Road  
Lynchburg, VA 24502-2498

For concerns related to Post-Construction Stormwater Management or for reporting pollution into stormwater runoff contact Ronald Parker, Facilities Manager, at 434-832-7740.



EEE Consulting, Inc.

**TABLE OF CONTENTS**

1.0 INTRODUCTION AND PURPOSE ..... 1

2.0 DOCUMENTATION REQUIREMENTS ..... 2

    2.1 Construction Record Drawings ..... 2

    2.2 BMP Inspection Forms ..... 2

    2.3 BMP Maintenance Follow-up Forms..... 2

    2.4 Annual Reporting to DEQ..... 3

3.0 INSPECTION FREQUENCY ..... 4

    3.1 DEQ Stormwater Inspector Certification ..... 4

4.0 STORMWATER MANAGEMENT FACILITIES ..... 5

    4.1 Bioretention ..... 5

    4.2 Detention ..... 6

5.0 BMP INSPECTION FORMS ..... 7

    5.1 Stormwater Management Facility Information ..... 7

    5.2 Inspection Elements..... 7

        5.2.1 Contributing Drainage Area ..... 7

        5.2.2 Pretreatment..... 8

        5.2.3 Inlets..... 8

        5.2.4 Sediment Forebay ..... 8

        5.2.5 Vegetation..... 8

        5.2.6 Emergency Spillway ..... 8

        5.2.7 BMP Outfall ..... 9

        5.2.8 Principle Spillway ..... 9

        5.2.9 Berm/Embankment..... 9

        5.2.10 Low Flow Orifice ..... 9

        5.2.11 Miscellaneous..... 9

6.0 FACILITY MAINTENANCE ..... 10

    6.1 Routine Maintenance ..... 10

    6.2 Corrective Maintenance ..... 10

**APPENDICES**

Appendix A: Stormwater Facility Inspection Forms

Appendix B: BMP Maintenance Follow-up Form

## ACRONYMS

BMP	Best Management Practice
CH	Virginia BMP Clearinghouse
CPESC	Certified Professional in Erosion and Sediment Control
CWA	Clean Water Act
DEQ	Virginia Department of Environmental Quality
EPA	Environmental Protection Agency
IDDE	Illicit Discharge Detection and Elimination
MEP	Maximum Extent Practicable
MS4	Municipal Separate Storm Sewer System
NEPA	National Environmental Policy Act
NPDES	National Pollutant Discharge Elimination System
SWPPP	Stormwater Pollution Prevention Plan
TMDL	Total Maximum Daily Load
VPDES	Virginia Pollutant Discharge Elimination System
VSMP	Virginia Stormwater Management Program

## 1.0 INTRODUCTION AND PURPOSE

Land development disturbs stable vegetated landscapes and increases impervious areas, which in turn increases the stormwater runoff from the land surface. Development also increases pollutant concentrations in stormwater runoff, as pollution associated with development is deposited onto hardened surfaces and carried by runoff into nearby water bodies. Such pollutants include sediment, suspended solids, nutrients, pesticides, herbicides, heavy metals, chlorides, hydrocarbons, other organics, and bacteria. To remove pollutants from stormwater runoff, structures are installed to reduce the pollutant loads using various processes. These stormwater structures are called Best Management Practices, commonly referred to as BMPs. They are designed to reduce flooding, remove pollutants and decrease the amount of stormwater runoff that ultimately flows into our creeks, streams, and rivers. Ensuring these BMP facilities function correctly requires long-term inspections and maintenance.

This manual presents the standard protocol for Post-Construction Stormwater Management Inspection and Maintenance procedures and satisfies the written procedures for long-term operation & maintenance (O&M) requirements of the small municipal separate storm sewer system (MS4) General Permit. As a regulated MS4, Central Virginia Community College (CVCC) is obligated to meet the requirements of the MS4 General Permit (General Permit). The General Permit is issued through the Virginia Pollutant Discharge Elimination System (VPDES), which is administered at the state level by the Virginia Department of Environmental Quality (DEQ). The MS4 program is part of the Federal National Pollutant Discharge Elimination System (NPDES), which is authorized through the Clean Water Act and regulated through the US Environmental Protection Agency (EPA).

CVCC's Post-Construction Stormwater Management Program, which is a series of written procedures in this manual, ensures adequate long-term operation and maintenance of BMPs for CVCC.

CVCC's Post-Construction Stormwater Management Program includes three distinct components:

- **Documentation** – Procedures to document efforts related to the Post-Construction Stormwater Management inspection and maintenance procedures are outlined in Section 2.0 of this manual.
- **Inspections** – Discussion of Post-Construction Stormwater Management facility types and components that require inspections are outlined in Section 4.0 of this manual. Instruction for the Post-Construction Stormwater Management Facility inspections are outlined in Section 5.0 of this manual. Stormwater facility inspection forms are provided in the Appendices.
- **Maintenance** – Discussion of typical maintenance requirements are provided in Section 6.0 of this manual.

## **2.0 DOCUMENTATION REQUIREMENTS**

Documentation of Post-Construction Stormwater Management efforts is critical for demonstrating compliance with the General Permit. All documentation related to Post-Construction Stormwater Management is required to be maintained on file and available upon request and include:

- Project Records, including stormwater plans (retain for 3 years);
- Construction Record Drawings (as-builts retain in perpetuity or until the BMP is removed);
- Completed BMP Inspection Forms (retain for 5 years); and
- Completed BMP Maintenance Follow-up Forms, when applicable (retain for 5 years).

Documentation listed above is incorporated into annual reporting as required by the General Permit.

### **2.1 Construction Record Drawings**

Upon completion of the construction of a stormwater BMP, a record drawing should be obtained. The record drawing, or as-built, serves the purpose of:

- Ensuring the BMP was built per the design plans and
- As a reference over time to assist with long-term inspection and maintenance.

Ideally, the record drawing would also prescribe inspection frequency and discuss critical maintenance needs. Information such as the design of the outfall structure, elevations, and vegetation plans will allow CVCC to restore the BMP to its original design, when necessary. Sometimes an issue with a BMP may not be evident during an inspection, such as if the facility should be holding water or be dry. A record drawing can be referenced to make that determination. Examples include, discovering the surface of an infiltration basin or a low-flow orifice being clogged, resulting in ponding. The intended function, such as time for water to drawdown out of the basin, may not be known until the record drawing is reviewed.

In some cases, especially with older facilities, a record drawing may not be available. In these cases, the Virginia BMP Clearinghouse can be referenced for additional information regarding inspections and maintenance of each type of stormwater BMP. The Clearinghouse can be found at:

<https://www.swbmp.vwrrc.vt.edu/>

### **2.2 BMP Inspection Forms**

The General Permit requires BMPs be inspected at a minimum once per year by CVCC. Completion of comprehensive inspection forms assists the inspector to:

- Inspect each critical component of the facility;
- Identify maintenance needs; and
- Properly document inspections to demonstrate compliance with the General Permit.

BMP inspection forms in Appendix A have been developed to assist the inspector, and unique forms are provided dependent on the type of BMP being inspected. In addition to the completion of the inspection forms, where applicable, a BMP Maintenance Follow-up Form should be completed as described in the next Section. Inspection forms are discussed in additional detail in Section 5.0 of this Manual.

### **2.3 BMP Maintenance Follow-up Forms**

In the case that issues are identified on BMP Inspection Forms, it is important to ensure the necessary maintenance is performed in a timely manner. It is critical that documentation demonstrating the completion of the maintenance is maintained on file to demonstrate compliance. This documentation

should be provided on the BMP Maintenance Follow-up Form in Appendix B. This Manual establishes time frames for completing maintenance needs identified during inspections. Time frames shall be designated by the Environmental Compliance Officer, or designee, and be prioritized based on the nature of the maintenance need. High prioritization should be given to situations that include issues with:

- BMP functionality regarding the potential to cause flooding (e.g., structural integrity of the embankment or clogged outflow structures);
- BMP functionality regarding the inability to remove pollutants as designed (e.g., clogged infiltration surface, dead vegetation); or
- BMP acting as a source of sediment (exposed soils requiring stabilization).

In the case of Corrective Maintenance, as identified in Section 6.2, a timeframe designation should be carefully considered by the Environmental Compliance Officer. In some cases, repairs may be necessary as soon as possible.

The Maintenance Follow-up Form is separated into two sections. The first section should be completed by the individual performing the BMP inspection. This section identifies the BMP, the inspection form on which an issue is identified, a description of the necessary maintenance, and an indicator of the severity of the issue(s) identified. The second section of the form is completed by the CVCC Environmental Compliance Officer and identifies who will perform the maintenance, sets a timeframe for performing the maintenance, and includes a description of the completed maintenance.

#### **2.4 Annual Reporting to DEQ**

CVCC must annually report to the DEQ information pertaining to its Post-Construction Stormwater Management efforts. Reporting requirements include the submittal of CVCC's Post-Construction Stormwater Management BMP electronic database that includes the following information:

- The stormwater management facility or BMP type;
- The stormwater management facility or BMPs location as latitude and longitude;
- The acres treated by the stormwater management facility or BMP, including total acres, pervious acres, and impervious acres;
- The date the facility was brought online (MM/YYYY). If the date brought online is not known, the permittee shall use June 30, 2005;
- The 6th Order Hydrologic Unit Code in which the stormwater management facility is located;
- Whether the stormwater management facility or BMP is owned or operated by the permittee or privately owned;
- Whether or not the stormwater management facility or BMP is part of the permittee's Chesapeake Bay TMDL action plan required in Part II A or local TMDL action plan required in Part II B, or both;
- If the stormwater management facility or BMP is privately owned, whether a maintenance agreement exists; and
- The date of the most recent inspection of the stormwater management facility or BMP.

The electronic database shall be updated no later than 30 days after a new BMP is brought online.

### **3.0 INSPECTION FREQUENCY**

The General Permit requires inspection of all stormwater management facilities at a minimum once per year. In addition to the annual inspections, the Virginia Stormwater Management Program and regulations require a stormwater facility inspection after any storm event that exceeds the principal spillway, or more specifically, whenever the emergency spillway is engaged.

Further, the inspection frequency may vary for a specific BMP if additional inspections are prescribed on the construction record drawings. This is oftentimes the case for the first year of a newly constructed BMP to ensure stabilization takes hold and any necessary plants survive.

#### **3.1 DEQ Stormwater Inspector Certification**

Individuals performing inspections of stormwater management facilities for CVCC are required to maintain a Stormwater Inspector Certification from DEQ. Information regarding the certification requirements is available at the DEQ Stormwater Certification webpage.


## 4.0 STORMWATER MANAGEMENT FACILITIES

This section describes the types of BMPs found on the CVCC campuses and their general layout and function. If additional BMPs are added to the campuses that differ in type, the manual will require updates to assist with compliance in accordance with Section 2.4 of this manual. Updates should be incorporated into the Manual within 1-year of the installation of the new BMP type.

There are several types of BMPs on the CVCC campuses. A discussion of the facility types is included in the following sections.

### 4.1 Bioretention

Bioretention facilities are shallow landscaped depressions that incorporate many of the pollutant removal mechanisms that operate in our natural environment. The primary component of a bioretention practice is the filter bed, which has a mixture of sand, soil, and organic material as the filtering media in the ground with a surface mulch layer. During storms, runoff temporarily ponds 6 to 12 inches above the mulch layer and then rapidly filters through the bed. Normally, the filtered runoff is collected in an underdrain and returned to the storm drain system or receiving channel. The underdrain consists of a perforated pipe in a gravel layer installed along the bottom of the filter bed. Bioretention facilities also can be designed to infiltrate runoff into native soils without an underdrain. This can be done at sites with permeable soils, a low groundwater table, and a low risk of groundwater contamination. The second most critical component of bioretention facilities is the landscaping plan and plantings. The plantings are designed specific to the site and facility and they remove and store pollution. Small residential applications of bioretention are termed rain gardens.



**Figure 1: Typical Bioretention Facility Section**

## 4.2 Detention

These basins have at least one inflow channel, an embankment/dam, a bottom level orifice, sometimes a riser in the basin, a principal spillway structure to route drainage through the dam, and an outlet structure. These basins do not have a normal pool and remain dry except during and shortly after storm events. Some extended detention facilities may have a wet marsh with plantings in the bottom for additional pollutant removal. On rare occasions the extended detention basin may be designed to have a wet normal pool. If a plan does not indicate a wet marsh or normal pool elevation, investigate to ensure a constant pool of water is not due to blockage.




Figure 2: Typical Dry Detention Basin Section

## **5.0 BMP INSPECTION FORMS**

BMP inspection forms are an integral part of the Post-Construction Stormwater Management Program and provide documentation to demonstrate compliance to the General Permit requirements. The following sections are intended to provide guidance when completing the BMP inspection forms located in Appendix A.

### **5.1 Stormwater Management Facility Information**

The following describes the general information required on the BMP inspection form:

- “Owner”: CVCC;
- “Facility ID #”: This is the facility identification # as identified on the IDDE & Post-Construction Stormwater Facility Map (incorporated by reference);
- “Inspection Date”: The date the inspection is taking place;
- “As-Built Plans Available”: Are the original As-Built plans available for reference? Indicate yes or no;
- “Date of Last Inspection”: The date of the last inspection of the facility. This information should be maintained on file and in the BMP inventory database;
- “Inspector(s)”: The name of the inspector performing the inspection;
- Determination if maintenance was required and performed that stemmed from a previous inspection. The inspector should be able to obtain and review the previous inspection form. During the current inspection, the inspector should be able to determine if previous maintenance items have been addressed; and
- Determination if maintenance is needed based on the current inspection. Maintenance would typically be required if “Yes” is selected for any of the issues on the form. In this case, a BMP Maintenance Follow-up Form should be submitted to the Environmental Compliance Officer.

### **5.2 Inspection Elements**

The inspection form is designed so that individual elements of the stormwater facility are inspected for the occurrence of typical issues. For each element issue, the inspector indicates a “yes,” “no,” or “N/A.” Where “yes” is indicated, the corresponding corrective action identified on the form needs to be scheduled. Proper evaluation of element issues is critical to identify maintenance needs; and therefore, preserve proper functionality of the BMP. The notes section of the form can be utilized to indicate the severity of maintenance needs. The following sections define and describe each component of the Inspection Form.

#### **5.2.1 Contributing Drainage Area**

The contributing drainage area includes any area that drains to the facility, both onsite and offsite. These areas should be examined as a potential source of trash, debris, or erosion if any of these are within the facility. Eliminating the source of the issue is essential and works as a preventative measure to ensure long term functionality of the BMP.

### **5.2.2 Pretreatment**

Pretreatment is the initial structure or measure through which stormwater runoff is routed before it enters the BMP. It serves as a preliminary filter, or trap, to remove silt and sediment that could reduce the pollutant removal efficiency of the BMP. As a result, the pretreatment structures or measures require clean out more often than the facility itself. If there are significant amounts of sediment in the pretreatment structure, it should be removed to maintain its function and to prevent the sediment from being re-suspended in runoff and conveyed to the BMP and subsequently downstream to the receiving waters.

### **5.2.3 Inlets**

Inlets, such as drop inlets and curb inlets, route runoff through the storm sewer and into BMPs for treatment from the contributing drainage area. The inspector should determine if sediment, trash, or other obstructions are preventing flow from being conveyed to the BMP.

### **5.2.4 Sediment Forebay**

A sediment forebay is a pretreatment structure that traps debris, trash, sediment and other pollutants from entering the BMP. Sediment must be cleaned out once the level in the forebay reaches 50% of the capacity. This can be measured by placing a marked stake in the forebay with the marking indicating the 50% level. The marker is useful since the forebay may often maintain a wet pool. Excessive sediment accumulation may also indicate exposed soils within the drainage area to the BMP that require stabilization.

### **5.2.5 Vegetation**

For certain BMPs, such as constructed wetlands, the planting plan serves as a component of the design. Vegetation assists with filtering and biological uptake of pollutants, and maintaining the plantings is critical to ensure functionality. The BMP vegetation should match the design plans for the number and species of plants present. Having more plants than what is shown on the plans is acceptable as long as it is not an invasive species and/or the overgrowth is not impacting the storage volume and the BMP's ability to drain. Mosquito breeding can also be a concern, especially once cattail matting has become established in the BMP. Therefore, cattails are not a desirable species within a BMP. Considering the general planting location in the facility is also helpful. For example, if there is a section of plants adjacent to a road shoulder that is dying, it may be indicative of contaminated runoff, such as from de-icing operations. Vegetation should be replaced in accordance with the approved plans, acceptable species and quantities from the Virginia BMP Clearinghouse for the BMP type, or as specified by a licensed Landscape Architect or Professional Engineer.

### **5.2.6 Emergency Spillway**

The emergency spillway is a channel that conveys stormwater during large storm events from the BMP to an outfall, usually the same one as the principal spillway or main outlet. It prevents the facility from overtopping during the large storm events. Not all facilities have an emergency spillway. Spillways can be lined with various materials including grass with or without erosion control matting, riprap, or concrete, based on the velocity of flows predicted through the spillway. The spillway is usually visible as a low spot a minimum of 1' below the top of embankment off to one side. Consult the design plans for additional details.

### **5.2.7 BMP Outfall**

The BMP outfall is the location where flows are discharged from the BMP. The BMP outfall should discharge into a stabilized receiving channel. At the location where the discharge from the BMP enters the receiving channel, there is typically a riprap stone lining to prevent erosion, otherwise known as outlet protection. The purpose of many stormwater facilities is to protect the downstream channels, and thus, an evaluation of the outfall and the channel immediately downstream should be conducted to determine if erosion is occurring.

### **5.2.8 Principle Spillway**

The principle spillway is the structure that controls how much flow exits the BMP during more frequent storm events. Flows typically pass through the control structure (e.g., orifice, riser) and subsequently through a culvert that passes through an embankment, if present. The principle spillway is used in most storm events, unlike the emergency spillway, which is only used during very large events. Because this is typically the only conveyance through the embankment, the functionality and structural integrity of the principle spillway is critical. Often, a riser may serve as the principal spillway and connect the discharge culvert to convey flows to the BMP outfall. The riser usually has a small opening, or orifice, that controls the amount of flow through the system. The functionality of the riser can have a large impact on the water level in the basin; and therefore, whether the designed pollutant removal is met. Larger storms may spill over the top of the riser through a grate. Inspections should ensure the top of the riser is free from obstruction as well as any orifices in the structure. Damage or deterioration can take the form of rust, cracking, exposed rebar, or additional holes in the structure.

### **5.2.9 Berm/Embankment**

The embankment or berm is the fill section that detains runoff within the facility. The face of the dam is the front side that interacts with the water level and the top, or crown, is the highest flat surface. The downstream side is the back of the dam from the top down to where the fill section meets the natural grade (called the “toe” of the dam), typically just below the outfall. Basins outlet on the downstream side, which can be a more problematic area due to the effects of water pressure and saturation on the face and through the embankment. Trees should not be allowed to grow in the embankment since their root systems can affect the structural integrity. A dug basin, however, will not have all of these components since it is excavated into the existing earth and not created by fill placement. Additionally, roadways are not considered embankments because they typically have culvert pipes through them to convey stormwater effectively. Issues with the embankment can be critical to the function of the facility, downstream safety, as well as environmental concerns in the case of a failure.

### **5.2.10 Low Flow Orifice**

The low flow orifice is the smaller outflow hole, usually in the riser, that slows the discharge from the pond, protecting against downstream erosion. It also provides settling time for the runoff within the facility. The low flow orifice tends to clog because of its small size and will typically have a trash rack or screen on the front of it.

### **5.2.11 Miscellaneous**

This section captures any other pertinent features or issues of the facility not otherwise addressed in the checklist. Issues may be identified in the footprint area and with general issues such as difficulty in accessing the BMP. Note any of the criteria needing repair and include applicable location information for reporting.

## **6.0 FACILITY MAINTENANCE**

The effectiveness of post-construction stormwater control BMPs depends upon regular inspections and maintenance of all aspects of the facility. There are typically two types of BMP maintenance, referred to as routine maintenance and corrective maintenance.

### **6.1 Routine Maintenance**

Routine maintenance consists of preventative measures that are essential to the ongoing care and upkeep of a BMP. These measures are performed regularly to ensure proper function. Additionally, it helps prevent potential nuisances (odors, mosquitoes, weeds, etc.), reduces the need for corrective maintenance, and reduces the chance of polluting stormwater runoff by identifying and repairing problems before they further deteriorate. Upon being identified during an inspection, routine maintenance should be conducted within six (6) months of the inspection.

Examples of routine maintenance include:

- Removal of any accumulated sediment from the forebays;
- Replacement of plants called for in the approved plans that have died or are diseased;
- Repair of the stormwater structures for erosion or undercutting;
- Repair of any erosion in the facility, including sloughing, animal burrows, and slopes;
- Repair of any deterioration at the outfall of the facility, including the riprap outlet protection;
- Removal of blockages from all trash racks, inlets, and outlets;
- Maintenance of adequate access to the facility and removal of woody vegetation as needed;
- Removal of trees from embankments;
- Exercise of valves to prevent them from locking up where applicable; or
- Removal all trash, debris, and floatables periodically from the facility.

### **6.2 Corrective Maintenance**

Corrective maintenance is any maintenance that should be addressed for the facility to properly function in accordance with the plans. These items require more intensive repair efforts and should be addressed as a higher priority than routine maintenance. If there are structural deficiencies, or issues that raise the water level in the facility beyond the design intentions, corrective maintenance is required and should be conducted as soon as possible to prevent downstream damage to properties and/or the environment. Upon being identified during an inspection, corrective maintenance should be conducted within one (1) year of the inspection contingent on complexity. Reasonable progress steps should at least be taken.

Examples of Corrective Maintenance include:

- Repair of any deterioration or issues with the principal spillway and riser, such as evidence of spalling, joint failure, leakage, corrosion, etc.;
- Extensive sediment removal when inspections indicate that 50% of the forebay sediment storage capacity has been filled;
- Control or removal of invasive species and plant growth if there are impacts to the storage volume (i.e., water levels rise because the vegetation is taking up the water storage space); or
- Removal of woody vegetation from the embankment, if present, to prevent structural damage.

Further information on maintenance recommendations for various types of BMPs can be found at the Virginia BMP Clearinghouse at: <http://www.vwrrc.vt.edu/swc/NonProprietaryBMPs.html>.

**Appendix A: Stormwater Facility Inspection Forms**

## BMP Operation & Maintenance Inspection for Detention, Retention and Extended Detention Basins

Owner Name:	Facility ID # (See Mapping):
Date of Inspection:	As-built plans available:      Y      N
Date of Last Inspection:	Inspector:
Were issues identified during the previous inspection that required maintenance?	Y      N
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?	Y      N
If no, explain:	
Does the current inspection, as summarized hereon, identified maintenance needs?	Y      N
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.	

BMP Element	Issue	Yes	No	N/A	Corrective Action
Contributing Drainage Area	Excessive trash/debris				Remove trash/debris and properly dispose.
	Bare exposed soil				Stabilize with seed and mulch. E&S measures may be warranted until stabilized.
	Evidence of erosion				Backfill area, seed, mulch and consider matting. E&S measures may be warranted until stabilized.
	Excessive landscape waste/yard clippings				Remove landscape waste and yard clippings to prevent clogging and properly dispose of them.
Pretreatment / Forebay / Inflow	Excessive trash/debris/sediment or other blockage				Remove trash/debris/sediment or blockages and properly dispose of.
	Dead vegetation, exposed soil				Replace vegetation and stabilize according to plans. E&S measures may be warranted until stabilized.
	Evidence of erosion, undercutting, or bare soils				Backfill area, seed, mulch and consider matting, E&S measures may be warranted until stabilized.
	Structural deterioration of inlets, outfalls or pretreatment overflow weirs into the facility				Repair and restabilize area. Consult plans for approved configuration or an engineer. E&S measures may be warranted until stabilized.
	Animal burrows				Fill in immediately and stabilize.
Aquatic Bench / Vegetation	Plantings inconsistent with approved plans.				Consult approved plans and/or management to ensure no approved plant substitutions were used. Remove unapproved plants and replace any required plantings in kind.
	Dead vegetation/exposed soil				Replace vegetation and stabilize according to plans. E&S measures may be warranted until stabilized.
	Invasive plants, such as cattails and phragmites, exceeds 15% of the planted area.				Invasive plants should be removed immediately. Vegetation may require periodic harvesting for proper long term management.

Berm/ Embankment	Overgrown, including woody growth 5' beyond the outfall pipe and/or embankment.			Removal of woody species near or on the embankment is critical for proper function and long term stability. Remove all woody growth including stumps. Consult an engineer for backfill specifications. Mow thick growth.
	There is sparse vegetative cover and erosion channels are present.			Backfill area with structural fill and consult engineer for proper specifications. Stabilize with seed and mulch, consider matting. E&S measures may be warranted until stabilized.
	Cracking, bulging, sloughing and seepage			Consult an engineer immediately to prevent failure.
	Evidence of animal burrows.			Fill in immediately and stabilize.
Riser	Structural condition of the riser is deteriorating.			Consult an engineer to recommend a repair and review the approved plans.
	Adjustable control valve inaccessible and inoperable (if present).			Repair valve to be operational.
	Pieces of the riser are broken or missing.			Repair immediately in accordance with the approved plans. Consult an engineer as needed.
	Riser or low flow orifice is blocked.			Remove blockage and properly dispose of.
	Riser provides inadequate conveyance out of facility.			Repair to properly convey drainage to the outfall per the approved plan. Consult an engineer as needed.
	Evidence of erosion or undermining at/around riser.			Repair erosion. Consult engineer for structural repairs as needed.
	Structural deterioration			Consult engineer for proper repair procedures.
Outlet / Outfall	Exposed rebar, joint failure, loss of joint material, misalignment, leaking or corrosion			Repair concrete to cover rebar. Consult engineer for all other structural repairs.
	Excessive trash/debris/sediment or blockages.			Remove trash/debris/sediment/blockages and properly dispose.
	Evidence of erosion and bare soil.			Backfill area, seed, mulch and consider matting, E&S measures may be warranted until stabilized.
	Valves, manholes or locks cannot be opened or operated (if present).			Repair/replace any broken fixtures.
	Erosion of outfall channel or riprap deterioration.			Repair and/or supplement riprap outlet protection in accordance with the approved plans.
	Outlets provide inadequate conveyance out of facility.			Repair to properly convey drainage to the outfall per the approved plan. Consult an engineer as needed.
Overall	Access to the facility is in need of repair.			Restore access for maintenance equipment per the approved plans.
	Encroachment on facility or easement by buildings or other structures.			Contact Facilities Planning
	Evidence of oil/chemical accumulation, odor, algae, color or pollution.			Report to management and consult IDDE manual.
	Fences and/or safety signage is inadequate.			Repair fences and signage for public safety.
	Trash in the pool			Remove immediately and observe safety procedures.
	Additional notes:			

### BMP Operation & Maintenance Inspection for Bioretention

Owner Name:	Facility ID # (See Mapping):
Date of Inspection:	As-built plans available:      Y      N
Date of Last Inspection:	Inspector:
Were issues identified during the previous inspection that required maintenance?	Y      N
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?	Y      N
If no, explain:	
Does the current inspection, as summarized hereon, identified maintenance needs?	Y      N
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.	

BMP Element	Problem	Yes	No	N/A	Corrective Action
Contributing Drainage Area	Excessive trash/debris				Remove trash/debris and properly dispose of.
	Bare exposed soil				Stabilize with seed and mulch. E&S measures may be warranted until the area is stabilized.
	Evidence of erosion				Backfill area, seed, mulch and consider matting. E&S measures may be warranted until stabilization.
	Excessive landscape waste/yard clippings				Remove landscape waste and yard clippings to prevent clogging and properly dispose of them.
Pretreatment (if applicable) & Inlets	Excessive trash/debris/sediment				Remove trash/debris/sediment and properly dispose of.
	Evidence of clogging				Rake material to determine level of clogging, removed clogged material and replace with clean material per the plan specifications.
	Dead vegetation, exposed soil				Replace vegetation and stabilize with seed and mulch according to plans. E&S measures may be warranted until area is stabilized.
	Evidence of erosion				Backfill area, seed, mulch and consider matting, E&S Measures may be warranted until stabilized.
	Evidence of ponding, noticeable odors, water stains, presence of algae or floating aquatic vegetation				Determine source of issue and remove/repair it. Consult management and the IDDE manual as needed.
	Inlets provide inadequate conveyance into facility				Repair inlets to drain to facility per plans.
	Presence of invasive species/weeds				Remove invasive species/weeds
Underdrain/pea gravel filter	Perforated pipe is not delivering conveyances as designed				Check if pipe is clogged with debris or woody root punctures. Manually clear out or replace pipe immediately.
	Evidence of standing water. Does not dewater between storms. Water ponds on the surface of basin for more than 48 hours after an event				This is an indication that underlying soil interface is clogged. This should be promptly investigated and addressed.
	Evidence of blockage				Determine source of blockage and promptly remove and dispose of.
	Litter is present within the practice				Remove immediately. Maintain contributing areas free of litter.

Outlet/ overflow spillway	Filter media is too low, compacted, or inconsistent with design specifications.			Consult an engineer or approved plans for the proper media mix specifications and placement guidance for repairs.
	Mulch is older than 3 years or in poor condition			Mulch shall be removed and replaced every 2-3 years.
Filter media	Chemicals, fertilizer and/or oil are present			No dumping of yard wastes into practice. Remove oil/grease from practice immediately and consult the IDDE Manual.
	Sediments are greater than 20% of design depth			Check plant health, manually remove sediment immediately without damaging plants.
	Exposed/bare soil			Stabilize with seed and mulch. E&S measures may be warranted until stabilization.
	Filter bed is blocked and/or filled inappropriately			Check blockage level by raking the layer and check the deposit depth. Consult the approved plan specifications and/or an engineer.
	Outlets provide inadequate conveyance out of facility			Repair conveyance. Consult engineering as needed.
	Excessive trash/debris/sediment accumulation at inlet			Remove trash/debris/sediment and properly dispose of.
	Evidence of erosion at/around inlet			Repair erosion and stabilize - consider matting.
	Maintenance access to facility in need of repair			Restore access for inspections and construction maintenance equipment.
Outlet	Access road needs maintenance to convey construction maintenance equipment.			Restore access for inspections and construction maintenance equipment.
	Structural components in need of repair			Consult Engineer and approved design plans.
	Hydraulic control components in need of repair			Consult Engineer and approved design plans.
Overall	Excessive trash/debris/sediment			Remove trash/debris/sediment and properly dispose of.
	Evidence of erosion			Backfill area, seed and mulch -consider matting, E&S Measures may be warranted until stabilized.
	Evidence of oil/chemical accumulation, odor, algae or color.			Report to management and consult IDDE manual.
	Encroachment on facility by buildings or other structures			Contact Facilities Planning
	Additional Notes:			

**Warning:** If any bioretention facility component has a watertight cover—be careful regarding the possibility of flammable gasses within the facility. Care should be taken lighting a match or smoking while inspecting facilities that are not vented. If the bioretention facility is in a completely enclosed vault the OSHA Confined Space Entry procedures must be followed.

Note: A customized maintenance schedule must be prepared for each bioretention facility, since the maintenance tasks will differ depending on the scale of bioretention, the landscaping template chosen, and the nature of the surface cover. The above is a general guideline only.

## BMP Operation & Maintenance Inspection for Permeable Pavement

Owner Name:	Facility ID # (See Mapping):
Date of Inspection:	As-built plans available:      Y      N
Date of Last Inspection:	Inspector:
Were issues identified during the previous inspection that required maintenance?	Y      N
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?	Y      N
If no, explain:	
Does the current inspection, as summarized hereon, identified maintenance needs?	Y      N
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.	

BMP Element	Problem	Yes	No	N/A	Corrective Action
Contributing Drainage Area	Excessive trash/debris				Remove trash/debris and properly dispose.
	Bare exposed soil				Stabilize soil with seed and mulch.
	Evidence of erosion				Backfill area, seed, mulch and consider matting. E&S measures may be warranted until stabilized.
	Excessive landscape waste/yard clippings				Remove landscape waste & yard clippings to prevent clogging.
Pretreatment	Maintenance access to pretreatment facility in need of repair				Restore access for inspections and construction equipment for repairs.
	Excessive trash/debris/sediment				Remove trash/debris/sediment and properly dispose.
	Dead vegetation, exposed soil				Stabilize according to plans. E&S measures may be warranted until area is stabilized.
	Evidence of erosion				Backfill area, seed and mulch. Consider matting, E&S Measures may be warranted until stabilized.
Inlets	Inlets provide inadequate conveyance into facility				Repair inlets to drain to facility.
	Excessive trash/debris/sediment accumulation at inlet				Remove trash/debris and properly dispose.
	Evidence of erosion at/around inlet				Backfill area, seed and mulch. Consider matting. E&S Measures may be warranted until stabilized.
Surface	Pavement is not draining precipitation/is clogged. Ponding water is visible on the surface 48 hours after a rain event. Significant amounts of sediment have accumulated between the pavers.				The surface shall be kept clean and free of leaves, debris and sediment. (Regular sweeping shall be implemented for porous asphalt or concrete systems)
Overflows or Emergency Spillways	Perforated pipe is not delivering conveyances as designed				Remove obstructions; identify sources of erosion and restabilize spillway.

Vegetation (where applicable)	Presence of invasive species/weeds.			Check plant health, manually remove sediment immediately without damaging plants.
	Dead vegetation/exposed soil			Backfill with soil, reseed, and protect area until vegetation is reestablished.
	Trees and shrubs are within 5 feet of pavement surface			Check that roots from trees have not penetrated the pavement, and leaves from deciduous trees and shrubs have not clogged the practice. Vegetation and large shrubs/trees that limit access or interfere with porous pavement operation shall be pruned.
	Filter bed is blocked and/or filled inappropriately			Redistribute soil substrate and remove sediments within two weeks.
Outlet	Outlets provide inadequate conveyance out of facility			Repair outlets for proper drainage.
	Excessive trash/debris/sediment accumulation at inlet			Remove trash/debris and properly dispose.
	Evidence of erosion at/around inlet			Backfill area, seed and mulch. Consider matting. E&S Measures may be warranted until stabilized.
Spill Prevention	Hazardous/toxic substances are located/used near or on pavement.			A spill prevention plan in areas where there is likelihood of spills from hazardous materials. Virtually all sites present potential danger from spills. All properties contain a wide variety of toxic materials including gasoline for lawn mowers, antifreeze for cars, solvents, pesticides, and cleaning aids than can adversely affect storm water if spilled. Releases of pollutants shall be corrected as soon as identified.
Access	Access is unsafe or impossible to inspect pavement			Egress and ingress routes shall be renovated to design standards. Roadways may need adjustments to accommodate size and weight of vehicles. Obstacles preventing maintenance personnel and/or equipment access to the porous pavement shall be removed. Gravel or ground cover shall be added if erosion occurs due to vehicular or pedestrian traffic.
Insects & Rodents	Insects and rodents are found within the practice.			Pest control measures shall be taken when insects/rodents are found to be present. Standing water that creates an environment for development of insect larvae shall be eliminated. If sprays are considered, than a mosquito larvicide, such as Bacillus thurengensis or Altoside formulations can be applied only if absolutely necessary. Holes in the ground located in and around the pervious pavement shall be filled and compacted.
Overall	Maintenance access to facility in need of repair			Restore access for inspections and construction equipment for repairs.
	Structural components in need of repair			Consult Engineer and approved design plans.
	Hydraulic control components in need of repair			Consult Engineer and approved design plans.
	Excessive trash/debris/sediment			Remove trash/debris/sediment and properly dispose.
	Evidences of erosion			Backfill area, seed and mulch. Consider matting. E&S Measures may be warranted until stabilized.
	Evidence of oil/chemical accumulation			Report to management and consult IDDE manual.
	Evidence of standing water; ponding, noticeable odors, water stains, presence of algae or floating aquatic vegetation			Report to management and consult IDDE manual.
	Additional Notes:			

## BMP Operation & Maintenance Inspection for Vegetated Roof

Owner Name:	Facility ID # (See Mapping):
Date of Inspection:	As-built plans available:      Y      N
Date of Last Inspection:	Inspector:
Were issues identified during the previous inspection that required maintenance?	Y      N
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?	Y      N
If no, explain:	
Does the current inspection, as summarized hereon, identified maintenance needs?	Y      N
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.	

BMP Element	Problem	Yes	No	N/A	Corrective Action
Vegetation	Plant cover is less than 90%.				Replace dead plantings per the approved plans.
	Debris, vegetative and non, is present.				Remove debris and properly dispose of, including clippings.
	Invasive and nuisance plant species are present.				Completely remove invasive plant species. Weeding shall be manual without the use of herbicides or pesticides.
	Plant bed is dry.				Hand water or use sprinkler system. Follow manufacturers' instructions for O&M. Shade or a water cloth maybe helpful in drought conditions.
Structural Components	Waterproof membrane is leaking or cracked.				Make necessary repairs immediately in accordance with approved plans. Consult engineer as needed.
	Root barrier is perforated.				Repair perforated area.
Drainage Layer/inlet pipes	Drain inlet pipe is in poor condition.				Repair as needed.
	Evidence of ponding, noticeable odors, water stains, presence of algae or floating aquatic vegetation.				Repair cause of standing water in accordance with approved plans. Changes from the approved plans must be reviewed by an engineer. Consult management and the IDDE manual as needed.
	Substrate/medium is not adequate to support healthy plant life.				Consult an engineer or approved plans for the proper media mix specifications and placement guidance for repairs.
	Inflow structures do not provide adequate conveyance to the treatment facility.				Repair structures to drain to facility per plans.
Soil substrate/ growing medium	Deterioration of facility's treatment area or condition.				Repair according to the approved plans, including the dimensions and specified conditions.
	Sediment accumulation.				Remove sediment and properly dispose of.
Overall	Threat of a spill from mechanical equipment or other roof storage items is imminent.				Spill prevention measures for roof systems shall be readily available and used. Correct releases of pollutants immediately in accordance with the IDDE manual.
	Evidence of erosion from wind or water.				Repair erosion and stabilize with additional soil substrate/growth medium and cover with approved plantings.
	Access to the Vegetated roof is unsafe or inefficient.				Restore access. Walkways shall be clear of obstructions and maintained to design standards.
	Evidence of damage or vandalism is present.				Repair as needed.
	Additional notes:				

## BMP Operation & Maintenance Inspection for **Infiltration Practices**

Owner Name:	Facility ID # (See Mapping):
Date of Inspection:	As-built plans available:      Y      N
Date of Last Inspection:	Inspector:
Were issues identified during the previous inspection that required maintenance?	Y      N
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?	Y      N
If no, explain:	
Does the current inspection, as summarized hereon, identified maintenance needs?	Y      N
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.	

BMP Element	Problem	Yes	No	N/A	Corrective Action
Contributing Drainage Area	Excessive trash/debris				Remove trash/debris and properly dispose.
	Bare exposed soil				Stabilize soil with seed and mulch.
	Evidence of erosion				Backfill area, seed, mulch and consider matting. E&S measures may be warranted until stabilized.
	Excessive landscape waste/yard clippings				Remove landscape waste and yard clippings to prevent clogging.
Pretreatment	Maintenance access to pretreatment facility in need of repair				Restore access for inspections and construction equipment for repairs.
	Excessive trash/debris/sediment				Remove trash/debris/sediment and properly dispose.
	Evidence of erosion				Backfill area, seed and mulch. Consider matting, E&S Measures may be warranted until stabilized.
	Evidence of clogging i.e. standing water; ponding, noticeable odors, water stains, presence of algae or floating aquatic vegetation				Sources of possible clogging shall be identified and corrected.
	Dead vegetation, exposed soil				Stabilize according to plans. E&S measures may be warranted until area is stabilized.
Inlets	Inlets provide stable conveyance into system				Make repairs to inlet as required.
	Excessive trash/debris/sediment accumulation at inlet				Remove trash/debris and properly dispose.
	Evidence of erosion at/around inlet				Sources of erosion shall be identified and controlled when native soil is exposed or erosion channels are present.
Basin inlet	Evidence of standing water. Does not dewater between storms. Water ponds on the surface of basin for more than 48 hours after an event				Inlet shall be cleared when conveyance capacity is plugged. Rock splash pads shall be replenished to prevent erosion.
Filter Media	Stormwater does not percolate uniformly through the trench. Water remains 48 hours after storm.				Filter media may need to be raked, excavated and cleaned, or gravel/soil shall be replaced to correct problem. Holes that are not consistent with the design and allow water to flow directly through the planter to the ground shall be plugged.
Embankment, Dikes, Berms and Side slopes	Water is not retained in the infiltration basin.				Slopes shall immediately be stabilized using appropriate erosion control measures when soil is exposed/flow channels are forming. Sources of erosion damage shall be identified and controlled.

Overflow or Emergency Spillways	Pipe does not successfully carry excess water to an approved receiving system.				Overflow pipe shall be cleared of sediment and debris when 50% of the conveyance capacity is plugged. Damaged pipes shall be repaired or replaced upon discovery.
Overflow or Emergency Spillways	The reservoir does not perform as per specifications.				Overflow shall be cleared when 25% of the conveyance capacity is plugged. Sources of erosion damage shall be identified and controlled when soil is exposed. Rocks or other armament shall be replaced when only one layer of rock exists.
Vegetation	Vegetation is not providing adequate filtering or is unable to protect underlying soils from erosion.				Mulch shall be replenished at least annually. Vegetation shall be replaced within a specific timeframe, e.g. three months, or immediately if required to maintain cover density and control erosion where soils are exposed.
	Nearby plants unrelated to the practice are interfering with the BMPs effectiveness.				Vegetation, large shrubs or trees that limit access or interfere with planter operation shall be pruned or removed. Fallen leaves and debris from deciduous plant foliage shall be raked and removed. Invasive vegetation contributing up to 25% of vegetation of all species shall be removed and replaced. Dead vegetation shall be removed to maintain less than 10% of area coverage or when planter function is impaired.
	Grass within practice is overgrown.				Grass shall be mowed to 4 –9 inches high and grass clippings shall be removed.
	Vegetative quality of the adjacent grass buffer is poor.				Spot reseed if cover is less than 90%.
	Plant composition inconsistent with approved plans.				Replace plant material according to approved plans or substitute appropriate plant species in accordance with the BMP Clearinghouse.
	Presence of invasive species/weeds.				Remove by hand with minimum damage to vegetation.
	Dead vegetation/exposed soil.				Remove and replace dead vegetaion according to approved plans. Cover exposed soil with appropriate material: vegetation, mulch or stone.
	Sediment/debris accumulation is more than 4 inches thick or so thick as to damage or kill vegetation.				Remove by hand with minimum damage to vegetation using proper erosion control measures. Litter and debris shall be removed routinely and upon discovery.
Observation Well	Condition of element is poor.				Replace observation well if needed and make sure it is still capped.
Sediment/ debris Management	The capacity volume of the bmp is compromised by sedimentation.				Sediment and debris exceeding 4" in depth shall be removed every 2–5 years or sooner if performance is affected.
Underdrain	The draw down rate should be measured at the observation well for three days following a storm event in excess of 0.5 inches in depth. If standing water is still observed after 48 hours, this is a clear sign that clogging is a problem.				Immediately clear debris from underdrain. It may need to be replaced.
Outlet	Outlets provide inadequate conveyance out of facility				Repair to properly convey drainage tooutfall per approved plan. Consult an engineer as needed.
	Excessive trash/debris/sediment accumulation at outlet				Remove trash/debris/sediment/blockages and properly dispose.
	Evidence of erosion at/around outlet				Backfill area, seed, mulch and consider matting, E&S measures may be warranted until stabilized.
Overall	Maintenance access to facility in need of repair				Remove woody vegetation and mow on regular basis.
	Additional notes:				

## BMP Operation & Maintenance Inspection for Manufactured Detention, Filter & Hydrodynamic Devices

Owner Name:	Facility ID # (See Mapping):
Date of Inspection:	As-built plans available:      Y      N
Date of Last Inspection:	Inspector:
Were issues identified during the previous inspection that required maintenance?      Y      N	
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?      Y      N	
If no, explain:	
Does the current inspection, as summarized hereon, identified maintenance needs?      Y      N	
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.	

BMP Element	Problem	Yes	No	N/A	Corrective Action
Contributing Drainage Area	Excessive trash/debris				Remove trash/debris and properly dispose.
	Bare exposed soil				Stabilize soil with seed and mulch.
	Evidence of erosion				Backfill area, seed, mulch and consider matting. E&S measures may be warranted until stabilized.
	Excessive landscape waste/yard clippings				Remove landscape waste and yard clippings to prevent clogging.
PreTreatment	Excessive trash/debris/sediment				Remove trash/debris and properly dispose.
	Evidence of erosion				Backfill area, seed, mulch and consider matting. E&S measures may be warranted until stabilized.
	Evidence of standing water; ponding, noticeable odors, water stains, presence of algae or floating aquatic vegetation				Sources of possible clogging shall be identified and corrected.
	Dead vegetation, exposed soil				Stabilize according to plans. E&S measures may be warranted until area is stabilized.
Inlets	Inlets provide stable conveyance into system				Make repairs to inlet as required.
	Excessive trash/debris/sediment accumulation at inlet				Remove trash/debris and properly dispose.
	Damage to box structure or grate				Repair minor damage. For major damage contact Manufacturer.
	Evidence of erosion at/around inlet				Sources of erosion shall be identified and controlled when native soil is exposed or erosion channels are present.
Downspout	Pipe is not delivering conveyances as designed				Remove debris. Damaged pipe shall be repaired.
Chambers	Sediment accumulation threshold has been reached.				Remove sediment and properly dispose.
	Trash and debris have accumulated in chambers.				Remove trash/debris and properly dispose.

Filter Media	Stormwater does not percolate uniformly through the planter. Water remains 48 hours after storm.			Filter media may need to be raked, excavated and cleaned, or gravel/soil shall be replaced to correct problem. Holes that are not consistent with the design and allow water to flow directly through the planter to the ground shall be plugged. Sources of possible clogging shall be identified and corrected.
	Sediment/debris accumulation is more than 4 inches thick or so thick as to damage or kill vegetation.			Remove by hand with minimum damage to vegetation using proper erosion control measures. Litter and debris shall be removed routinely and upon discovery.
	Mulch is significantly diminished			Add double shredded mulch evenly across the entire unit to a depth of 3"
	Erosion control stones are not correctly placed			Reposition to allow for entry of trash during a storm event.
Vegetation	Dead vegetation			Replace plant in accordance with approved plans.
	Plant health is poor			Prune as needed, ensure planted well i.e. not leaning or exposed rootzone, check for diseases or pests.
	Vegetative quality of the adjacent grass buffer is poor.			Spot reseed if cover is less than 90%.
	Presence of invasive species/weeds.			Remove by hand with minimum damage to vegetation.
Outlet	Outlets provide inadequate conveyance out of facility			Repair to properly convey drainage to the outfall per the approved plan. Consult an engineer as needed.
	Excessive trash/debris/sediment accumulation at outlet			Remove trash/debris/sediment/blockages and properly dispose.
	Evidence of erosion at/around outlet			Backfill area, seed, mulch and consider matting, E&S measures may be warranted until stabilized.
Overall	Maintenance access to facility in need of repair			Remove woody vegetation and mow on regular basis.
	Encroachment on facility or easement by buildings or other structures			Contact Facilities Planning
	Additional notes:			

**Warning:** If any manufactured structure has a watertight cover—be careful regarding the possibility of flammable gasses within the facility. Care should be taken lighting a match or smoking while inspecting facilities that are not vented. If the structure is in a completely enclosed vault the OSHA Confined Space Entry procedures must be followed.

Note: A customized maintenance schedule must be prepared for each manufactured structure, since the maintenance tasks will differ depending on the function. The above is a general guideline only.

## BMP Operation & Maintenance Inspection for Rainwater Harvesting

Owner Name:		Facility ID # (See Mapping):			
Date of Inspection:		As-built plans available:		Y	N
Date of Last Inspection:		Inspector:			
Were issues identified during the previous inspection that required maintenance?		Y	N		
If so, was the maintenance performed and recorded on a BMP Maintenance Follow-up Form?		Y	N		
If no, explain:					
Does the current inspection, as summarized hereon, identified maintenance needs?		Y	N		
If yes, please complete a BMP Maintenance Follow-up Form and provide to the Director of Facilities upon completion.					
BMP Element	Problem	Yes	No	N/A	Corrective Action
Pretreatment	Gutters, downspouts and inflow devices blocked?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Remove all blockages from inflow structures.
	Screens, first flush diverters or vents blocked?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Removal all debris and blockages.
	Vegetation overhanging structures and creating debris/blockages?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Trim all overhanging vegetation to limit the amount of vegetative debris and blockages.
Structural Components	Sediment build up in tank?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Remove sediment and locate source as preventative measure. See above section.
	Structural integrity of the tank, pumps or electrical systems has deteriorated?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Repair in accordance with the approved plans. Consult an engineer as needed.
	Backflow preventer not properly functioning?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Repair in accordance with the approved plans. Consult an engineer as needed.
Outlets	Overflow pipes and paths are not properly functioning?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Restore overflow features per the designed plans. Consult the approved plans and an engineer as needed.
	Outflow spigot blocked?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	Remove blockage.
Overall	Additional notes:				

**Appendix B: BMP Maintenance Follow-up Form**

# BMP Maintenance Follow-up FORM

## Information from inspection

Campus: \_\_\_\_\_ BMP ID # (see campus BMP Inventory map): \_\_\_\_\_

Was the maintenance need generated from an inspection? \_\_\_\_\_ If yes, date on inspection form: \_\_\_\_\_

Description of required maintenance: \_\_\_\_\_

\_\_\_\_\_

Is maintenance critical to the function of the BMP?  Yes  No  Not sure

## Information from maintenance

Individual performing or overseeing maintenance: \_\_\_\_\_

Requested date for maintenance to be completed by: \_\_\_\_\_

Date(s) maintenance completed: \_\_\_\_\_

Did maintenance solve the identified problem?  Yes  No  Not sure

If no or not sure, describe further necessary maintenance and a date for the additional maintenance to be performed:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Description of maintenance performed: \_\_\_\_\_

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Attach photographs to this form and retain for records.